

City of Tacoma Hylebos



Elevation View

City of Tacoma Hylebos



Deck View

City of Tacoma Hylebos



View of Approach Span

Grays Harbor County Cloquallum Creek



Elevation View

Grays Harbor County Cloquallum Creek



Deck View

Grays Harbor County Cloquallum Creek



View of Substructure



Grays Harbor
County
Cloquallum
Creek

Failing
Timber Pile

Snohomish County South Slough Bridge




Elevation View

Snohomish County South Slough Bridge



Deck View

Snohomish County South Slough Bridge



Typical Concrete Deterioration

Snohomish County South Slough Bridge



Soffit View

Snohomish County South Slough Bridge



Leaching Cracks in Soffit

Thurston County Hays Bridge



Deck View

Thurston County Hays Bridge



View Looking South

Thurston County Hays Bridge



View Looking North